FIG. 1





FIG. 2







FIG. 4






FIG. 6





FIG. 7







FIG. 8







FIG. 9






FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20

201

PAPER JAM OCCURRED IN MAIN BODY. MOVE BOTH-SIDED UNIT.

FIG. 21







FIG. 22

201

HIGH CAPACITY TRAY IS OUT OF PAPER. SUPPLY PAPER.









SCANNER FUNCTION IS IN FAILURE.

FIG. 26 (a)

201

SCANNER FUNCTION IS IN FAILURE.

FIG. 26 (b)

201

PRINTING

OKAMOTO MS-WORD





FIG. 28






FIG. 29 (b)




FIG. 30




FIG. 31

